
ARMSTRONG PIPE THREADING MACHINES.



No. O Hand Machine ¼ to 2, R. H. Pipe, \$60.00

,, O ,, ,, ½ to 1½ Bolts, . . . 60.00

,, O Power Machine ½ to 1½, Bolts, . . 103.00

,, O ,, , ¼ to 2, R. H. Pipe, 103.00

Stand for above Machine, 10.00


No. OO Hand Machine I to 4, R. H. Pipe, 125.00

,, OO Power Machine I to 4 R. H. ,, 195.00

Stand for above Machine

No. 1 Hand Machine 1 to 3, R. H. Pipe, . . . \$115.00

No. 1 Power Machine 1 to 3, R. H. Pipe, . . . 170.00





No 11/2 Power Machine

Threads Pipe 1 to 4, R. H. . . . \$316.00

No. 3 Power Machine

Threads Pipe 1 to 6, R. H. . . . 550.00

All these Machines are Adjustable to Variations in Fittings.

ARMSTRONG ADJUSTABLE STOCKS AND DIES.



STOCK WITH


4 R. H. Pipe Dies, 1/8 to 1/2 each, \$9.00
4 Each, R. and L. Pipe Dies,
1/8 to 1/2 each, 14.00
7 Bolt Dies, ¼ to ¾ 15.00
4 Pipe and 7 Bolt Dies, 20.00
7 Bolt Dies, 7 Taps 1/4 to 3/4 20.00
4 Pipe Dies, 7 Bolt Dies, 7-
Taps, 24.80
Sizes Eumiched in Polt Dies

 $\frac{1}{4}$, $\frac{5}{10}$, $\frac{3}{8}$, $\frac{7}{16}$, $\frac{1}{2}$, $\frac{5}{8}$, $\frac{3}{4}$, other sizes Special. This Stock will not take Bolt sizes

smaller than 1/4, nor larger than 3/4.

No 2 STOCK WITH

No. 2 STOCK WILL
5 Pipe Dies, ¼ to 1, \$12.00
6 Pipe Dies, ½ to 1, 14.00
5 Pipe Dies, Right and Left,
¼ to I, 20.00
6 Pipe Dies, Right and Left,
½ to I, 23.00
7 Bolt Dies, ½ to 1¼, 20.00
7 Bolt ½ to 1¼, and 5 Pipe
Dies ¼ to 1, 28.50
7 Bolt Dies, 7 Taps ½ to 1¼, . 30.00
7 Bolt Dies, 7 Taps ½ to 1¼
and 5 Pipe Dies 1/ to T 28 75



No. 21/2 STOCK WITH

4 Dies, cutting 1/2, 3/4, I, and 14, Right Hand, \$12.00 Dies cutting 1/2 to 1 1/4 R. and L. 18.00 Pipe Dies, single end, 1/2 or 3/8. 3.00

No. 3 STOCK WITH

3 Sizes Pipe Dies, 11/2 to 2, R. H. 20.00 ,, I to 2, R. H. 24.00 3/4 to 2, R. H. 28.50 " 11/4 to 2 Right 32.00 4 Sizes Pipe Dies, I to 2 Right and Left, 40.00 5 Sizes Pipe Dies, 3/4 to 2, Right and Left, 48.50

No. 6 STOCK WITH

Die cutting 21/2 x 3, Right, . . 40.00 21/2 x 3, R. and L. . 55.00 The change from 21/2 to 3, is made by reversing Dies end for end, when

they will cut 2 standard sizes without No. 7 STOCK WITH

further adjustment.

Dies cutting 21/2, 3, 31/2 and 4 R. 60.00 2½ and 3, ,, . . 45.00 3½ ,, 4, ,, . . 45.00 21/2 to 4, R. and L. 92.00 2½, 3 or 3½ and 4, Right and Left, 60.00

These Dies come in Sets of four pieces, each piece being Double ended.

ARMSTRONG HINGED VISES.

	No. 1 will hold from O to 2½ Pipe,
	{ 56, 34 or 36 O. Dia., }
	{ 138, 1½ or 156 O. Dia., }
PIPE	1¼, 1½ or 2 I. P. Size, [

No. 3	Takes	from	0	to I	\$2.00
No. 4	,,	,,	0	to 1 ½	. 2.75
No. 5	,,	,,	3/8	to 2½	. 4.50
No. 6	,,	1,	I	to 4 .	12.00



NIPPLE HOLDER FOR STOCKS.

For No. 2 Stock 3/8 x 1/2 or 3/4 x 1 each, \$3.00 $\frac{1}{2}$, $\frac{1}{2}$ x $\frac{3}{4}$ or I x I $\frac{1}{4}$... 3.00 $,, 3 ,, I \times I \frac{1}{4} \text{ or } I \frac{1}{2} \times 2 ,, . . 3.50$ $,, 6 ,, 2^{1/2} \times 3$,, . . 8.00

7 ,, $2\frac{1}{2} \times 3$ or $3\frac{1}{2} \times 4$, . . 8.00

BARD ADJUSTABLE BUSHINGS,

To take the place of ordinary Ring Bushings.

No. 1 For	Stocks	threadin	ıg Pipe	½ in.	down	each, . \$4.50	
No. 2 ,,	,,	,,	,,	ı ,,	,,	,, 5.00	The last
No. 2½,,	,,	,,	,, I	¼ "	,,	,, 6.00	
No. 3 ,,	>>	,,	. ,,	2 ,,	,,	,, 8.00	SIP
No. 3 with	Leade	r Screw,				10.00	SAIDCEPORT COM